



This left hand propeller is in the forward drive position with it's Blades set at the correct pitch angle of 18 degrees.

If the propeller is assembled 1 tooth out from the correct position The pitch angle will be too much at over 25 degrees or Not enough at less than 10 degrees.