



This is a right hand propeller in the forward drive position
With it's blades set at the correct angle of 18 degrees.

If you assemble the propeller 1 tooth out from the correct
Position the blade angle will be too much at over 25 degrees
Or the angle could be not enough at less than 10 degrees.